

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1540
East
> 1
1.936 mi.
10220 ft.

IN FRONT OF
12 KENSINGTON ST
BROOKLYN, NY

NY Spills S106697897
N/A

Relative:
Higher

Actual:
0 ft.

SPILLS:

Name: IN FRONT OF
Address: 12 KENSINGTON ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0404767 / 2004-10-21
Facility ID: 0404767
Facility Type: ER
DER Facility ID: 194411
Site ID: 235999
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2004-08-01
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2004-08-01
CID: 64
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-08-01
Spill Record Last Update: 2004-10-21
Spiller Name: ERT DESK
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 999

Contact Name:

ERT DESK

DEC Memo:

"e2mis no. 154634: APPROX 3-GALLONS OF TRANSFORMER OIL LEAKED FROM TM-SERIAL#2-3758 ONTO SIDEWALK & STREET ALSO REPORTS AREA OF 10' BY 10' GRASS F/O 120 KENSINGTON ST. RECORDS SHOW 2 PPM DATED 8/18/93. UNABLE TO TAKE SAMPLE AT THIS TIME DUE TO FEEDER NEED TO BE TAKEN OFF SYSTEM. OVERHEAD #9 WAS DISPATCHED. 8/2/04 0055 HRS. LINEMAN BAGGED TM IT IS NOT LEAKING AT THIS TIME .ALSO REPORTS GRASS AFFECTED WITH OIL AN AREA OF 2' BY 10' ENVIR OPPS WILL DIG 6 X 2' BY 10' AREA OF DIRT. UNABLE TO TAKE SAMPLE FROM TRANSFORMER AT THIS TIME DUE TO OIL STILL BOILING. 1-SOIL SAMPLE WILL BE TAKEN. 8/2/04 0405HRS O.S.GENE WILLIAMS ENVIR REPORTS SIDEWALK AND STREET DOULBED WASHED USING BIO-GEN 760. ALL THE GRASS & SOIL WAS REMOVED AND PLACED INTO 2-DRUMS. PENDING RETURN OF SOIL SAMPLE. OVERHEAD TO REPLACE TRANSFOMER. Lab Sequence Number: 04-06026-001: PCBs < 1 ppm UPDATE 8/2/04 10:15 HRS R. TUCKER #12264 O/H SUPV REPORTS THE UNIT HAS BEEN TAKEN DOWN AND BAGGED, THE UNIT IS NOT LEAKING, A SAMPLE WAS TAKEN FROM THE UNIT AND GIVEN TO ENV OPS CREW ON LOCATION, AND A NEW UNIT IS BEING INSTALLED. INCIDENT TO REMAIN OPEN PENDING LAB SAMPLE FROM UNIT. 8/2/04 1811HRS LAB RESULT RETUNERD <1.PPM LSN-04-06038-001 INCIDENT WILL CLOSED AS A RESULT OF SAMPLE."

Remarks:

"NO TO 5 QUESTIONS: CON-ED #154634"

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

All Materials:

Site ID:	235999
Operable Unit ID:	888150
Operable Unit:	01
Material ID:	488748
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported